

7<sup>th</sup> April 2020  
Our ref: GCU0257001/GW/JW

ESB Networks  
Engineering Major Projects  
One Dublin Airport Central  
Dublin Airport  
Cloghran  
Co. Dublin

**Subject: Historic Cable Fluid Losses – Location 25  
Recommendations from Preliminary Site Assessment**

Dear Sir/Madam

We refer to our Preliminary Site Assessment (PSA) report on the historic loss of cable fluid in Terenure, Dublin 6W (Location 25) dated 7<sup>th</sup> April 2020. The PSA identified the following potential receptors and preliminary risk categories linked to the cable fluid loss<sup>1</sup>:

- |                        |   |     |
|------------------------|---|-----|
| • River Dodder         | - | Low |
| • Bushy Park Duck Pond |   | Low |
| • Water mains          | - | Low |
| • Bedrock aquifer      | - | Low |

Based on the findings of the PSA, no further investigations are considered necessary.

Yours sincerely for  
Geosyntec Consultants Ltd

  
Principal Environmental Engineer

<sup>1</sup> The preliminary risk categories were determined by applying the risk assessment methodology outlined in CIRIA publication C552 (2001).