



20 April 2020

Project No. 19126590.L37.A.1

**ESB Networks**

Engineering and Major Projects  
One Dublin Airport Central  
Dublin Airport  
Cloghran  
County Dublin  
K67 XF72

**RE ESB SITE 37 PARKVIEW TO RINGSEND 38KV CABLE FLUID LOSS: RECOMMENDATIONS**

To whom it may concern

ESB Engineering and Major Projects (ESB) commissioned Golder Associates Ireland Limited (Golder) to complete a Preliminary Site Assessment (PSA) for historical loss of fluid from a high voltage (38 kV) cable run located between Parkview and Ringsend, Dublin ('Site 37') (hereafter referred to as the 'Site').

The PSA was produced in-line with current EPA guidance (*Guidance on the management of contaminated land*, 2013). The findings of the PSA were presented in our report reference 19126590.37.A.1 dated 20 April 2020.

The risk assessment completed for this site did not identify viable pollutant linkages. Golder does not recommend any follow up actions in relation to the loss of 100 L of cable fluid in 2008 at this site as detailed in the report referenced above.

Yours sincerely,

**Golder Associates Ireland Limited**

  
*Senior Hydrogeologist*

  
*Geo Environmental Director*

EMcA/TM/mb