



9 June 2020

Project No. 19126590.L47.A.2

ESB Networks

Engineering and Major Projects
One Dublin Airport Central
Dublin Airport
Cloghran
County Dublin
K67 XF72

RE ESB SITE 47 EAST WALL ROAD TO RINGSEND 38KV CABLE FLUID LOSS: RECOMMENDATIONS

To whom it may concern

ESB Engineering and Major Projects (ESB) commissioned Golder Associates Ireland Limited (Golder) to complete a Preliminary Site Assessment (PSA) for historical loss of fluid from a high voltage (38 kV) cable run located between East Wall Road and Ringsend, Dublin ('Site 47') (hereafter referred to as the 'Site').

The PSA was produced in-line with current EPA guidance (*Guidance on the management of contaminated land*, 2013). The findings of the PSA were presented in our report reference 19126590.47.A.2 dated 9 June 2020.

The risk assessment completed for this site did not identify viable pollutant linkages. Golder does not recommend any follow up actions in relation to the loss of 390 L of cable fluid in 2007 at this site.

Yours faithfully

Golder Associates Ireland Limited

██████████
Geo Environmental Engineer

██████████
Geo Environmental Director

GF/TM/ab